













# Hyundai Avante, 2018

VIN: KMHD641DBJU523198      Report ID: 251d9e7f928774e7112631528bca2e3c

Report Date: 2025-02-20

## General Information

⚠️ 8/12 attention marks

 <b>Odometer records</b> 38,909 km ⚠️	 <b>Number of owners</b> 6 owner(s) ⚠️	 <b>Taxi</b> No records found ✓
 <b>Sales history</b> 2 record(s) ⚠️	 <b>Total destruction</b> No records found ✓	 <b>Flood insurance</b> No records found ✓
 <b>Special purpose history</b> Found record(s) ⚠️	 <b>Change car number</b> Found record(s) ⚠️	 <b>Damage to this car by another car</b> 2 ⓘ ⚠️
 <b>Damage to another car by this car</b> 2 ⓘ ⚠️	 <b>Rental history</b> Found record(s) ⚠️	 <b>History of public use</b> No records found ✓

Found 29 photos

(2 auctions)









































## Vehicle Specifications

 Year	2018	 Fuel type	Gasoline
 Country	KR	 Drive Type	Front-wheel Drive
 Make	Hyundai	 Transmission	-
 Model	Avante	 Keys	YES
 Body	Sedan	 Height	-
 Doors	4	 Length	-
 Color	?? ???	 Width	-
 Engine capacity	1.6L		
 Standard seating	-		

# Advanced Safety Devices

✓ 7 installed

	Anti-lock Braking System (ABS)	Installed
	Automatic Emergency Braking (AEB)	Not Available
	Parking Steering Brake Support	Not Available
	Rear Cross Traffic Alert (RCTA)	Installed
	Vehicle Stability Control System	Installed
	Lane Departure Warning System (LDWS)	Not Available
	Front and Rear Parking Sensors	Not Available
	Around View	Not Installed
	Emergency Brake Warning System	Not Installed
	Rearview Camera (BCAM)	Not Available
	Built-in Camera	Not Installed
	Forward Collision Warning System (FCWS)	Not Available
	Lane Departure Warning System (LDWS)	Not Available
	Parking Steering Assist System	Not Available
	Adaptive Cruise Control (ACC)	Not Available
	Adaptive Headlights	Not Available
	Brake Assist System	Installed
	Daytime Running Lights	Installed
	Head-Up Display	Not Installed
	TPMS	Installed
	Rear Parking Sensors	Installed

# Ownership history

⚠ 6 owner(s)



## 6 owner

- Mileage -
- Change number -
- Change owner Information provision ended
- Vehicle use -
- Date record 2025-01-22



## 5 owner

- Mileage -
- Change number -
- Change owner Owner change
- Vehicle use Private car
- Date record 2021-02-08



## 4 owner

- Mileage -
- Change number -
- Change owner Owner change
- Vehicle use Private car
- Date record 2021-01-27



## 3 owner

- Mileage -
- Change number -
- Change owner Owner change
- Vehicle use Private car
- Date record 2021-01-25



## 2 owner

Mileage -

Change number 176?XXXX

Change owner Change owner and number

Vehicle use Private car

Date record 2021-01-25



## 1 owner

Mileage -

Change number 60?XXXX

Change owner First registration

Vehicle use Business car

Date record 2017-10-17

# Mileages

✓ 2 record(s)

- 2021-02-06  
38909 km
- 2021-01-26  
38908 km








# Vehicle damages

2024-04-30

## DAMAGE INFO

⚙ Damage 1	Front Bumper	Stamps
⚙ Damage 2	Radiator Grille	Detach





## Damage history

### **XX** Replacement

New part installed, painted

### **pp** Repainted

Repainted

## Present defects

### **f** Dent

Small dent

### **w** Repaired

Part repaired, painted

### **m** The part was disassembled

The part was disassembled

### **x** Replacement required

Needs replacement due to dents, chips and scratches

### **P** Repainting required

Repainting is required due to chips or scratches

### **Q** Repair required

Parts need to be repaired

### **C** Corrosion

Corrosion

### **A** Polishing required

Detail with minor scratches




# Accident records

2 accident(s)

2024-04-30

## Accident #2




Accident vehicle 1 (this vehicle)	
 Detail	232 USD
 Wages	85 USD
 Painting	0 USD
<hr/>	
Total Repair (estimate) cost	316 USD

Accident vehicle 2 (participant in an accident)	
 Detail	97 USD
 Wages	209 USD
 Painting	0 USD
<hr/>	
Total Repair (estimate) cost	306 USD

2017-11-19

## Accident #1

Accident vehicle 1 (this vehicle)	
 Detail	207 USD
 Wages	58 USD
 Painting	0 USD
<hr/>	
Total Repair (estimate) cost	266 USD

Accident vehicle 2 (participant in an accident)	
 Detail	756 USD
 Wages	0 USD
 Painting	0 USD
<hr/>	
Total Repair (estimate) cost	756 USD

## Export from Korea

✓ Found record(s)



Mileage  
**84,834 km**



Date first registration 2017-10-17



Last first registration 2025-01-22



Date registration cancellation 2025-01-22



Appointment of deregistration



Damaged

## Average export sales

✓ No records found

## Technical inspection

✓ Found record(s)



Date from 2023-10-17



Date to 2025-10-16



Mileage 84,834 km

## Auction sale history

⚠ 2 record(s)

### Sold #2

12826 USD



38,909 km



CARMANAGER.CO.KR



2021-02-06















#### VEHICLE INFO

-  Make Hyundai
-  Model Avante
-  Year 2018
-  Engine capacity 1.6L
-  Body Sedan
-  Transmission -

#### Sold #1







10943 USD    38,908 km    GLOVISAA.COM    2021-01-26







#### VEHICLE INFO

-  Make Hyundai
-  Model Avante
-  Year 2018
-  Engine capacity 1.6L
-  Body Sedan
-  Transmission -